





















Вычисление числа степеней свободы механической системы

Определить число степеней свободы системы по формуле $W = 3Д - 2Ш - С$.

<p>Вариант 1 Д22.</p>	<p>Вариант 2 Д22.</p>
<p>Вариант 3 Д22.</p>	<p>Вариант 4 Д22.</p>
<p>Вариант 5 Д22.</p>	<p>Вариант 6 Д22.</p>
<p>Вариант 7 Д22.</p>	<p>Вариант 8 Д22.</p>
<p>Вариант 9 Д22.</p>	<p>Вариант 10 Д22.</p>





Ответы

1	2
2	4
3	3
4	2
5	1
6	-1
7	1
8	2
9	6
10	3
11	1
12	2
13	4
14	2
15	5
16	3
17	2
18	1
19	2
20	1
21	2
22	0
23	3
24	5
25	4
26	2
27	2
28	3
29	1
30	4