



















Вычисление числа степеней свободы механической системы

Определить число степеней свободы системы по формуле $W = 3Д - 2Ш - С$.

<p>Вариант 1 Д22.</p> 	<p>Вариант 2 Д22.</p> 
<p>Вариант 3 Д22.</p> 	<p>Вариант 4 Д22.</p> 
<p>Вариант 5 Д22.</p> 	<p>Вариант 6 Д22.</p> 
<p>Вариант 7 Д22.</p> 	<p>Вариант 8 Д22.</p> 
<p>Вариант 9 Д22.</p> 	<p>Вариант 10 Д22.</p> 



Ответы

1	3
2	1
3	4
4	3
5	6
6	2
7	1
8	0
9	3
10	2
11	-1
12	3
13	3
14	1
15	-1
16	3
17	0
18	1
19	5
20	3
21	3
22	4
23	1
24	1
25	0
26	-1
27	3
28	0
29	2
30	1