































Вычисление числа степеней свободы механической системы

Определить число степеней свободы системы по формуле $W = 3Д - 2Ш - С$.

<p>Вариант 1 Д22.</p> 	<p>Вариант 2 Д22.</p> 
<p>Вариант 3 Д22.</p> 	<p>Вариант 4 Д22.</p> 
<p>Вариант 5 Д22.</p> 	<p>Вариант 6 Д22.</p> 
<p>Вариант 7 Д22.</p> 	<p>Вариант 8 Д22.</p> 
<p>Вариант 9 Д22.</p> 	<p>Вариант 10 Д22.</p> 





Ответы

1	5
2	4
3	0
4	-2
5	1
6	2
7	0
8	1
9	4
10	5
11	2
12	1
13	2
14	1
15	3
16	-2
17	4
18	2
19	1
20	2
21	1
22	4
23	2
24	1
25	2
26	2
27	4
28	4
29	3
30	4