































## Вычисление числа степеней свободы механической системы

Определить число степеней свободы системы по формуле  $W = 3D - 2Ш - С$ .

<p><b>Вариант 1</b> Д22.</p> 	<p><b>Вариант 2</b> Д22.</p> 
<p><b>Вариант 3</b> Д22.</p> 	<p><b>Вариант 4</b> Д22.</p> 
<p><b>Вариант 5</b> Д22.</p> 	<p><b>Вариант 6</b> Д22.</p> 
<p><b>Вариант 7</b> Д22.</p> 	<p><b>Вариант 8</b> Д22.</p> 
<p><b>Вариант 9</b> Д22.</p> 	<p><b>Вариант 10</b> Д22.</p> 





Ответы

1	4
2	4
3	2
4	4
5	2
6	-1
7	3
8	2
9	4
10	3
11	5
12	3
13	4
14	1
15	0
16	2
17	5
18	4
19	3
20	2
21	-2
22	0
23	2
24	2
25	-1
26	2
27	3
28	1
29	3
30	3