































Вычисление числа степеней свободы механической системы

Определить число степеней свободы системы по формуле $W = 3Д - 2Ш - С$.

<p>Вариант 1 Д22.</p> 	<p>Вариант 2 Д22.</p> 
<p>Вариант 3 Д22.</p> 	<p>Вариант 4 Д22.</p> 
<p>Вариант 5 Д22.</p> 	<p>Вариант 6 Д22.</p> 
<p>Вариант 7 Д22.</p> 	<p>Вариант 8 Д22.</p> 
<p>Вариант 9 Д22.</p> 	<p>Вариант 10 Д22.</p> 





Ответы

1	4
2	-2
3	3
4	2
5	3
6	3
7	3
8	0
9	4
10	0
11	5
12	2
13	3
14	5
15	2
16	3
17	1
18	3
19	1
20	3
21	1
22	0
23	3
24	5
25	0
26	-2
27	0
28	3
29	3
30	2