































Вычисление числа степеней свободы механической системы

Определить число степеней свободы системы по формуле $W = 3D - 2Ш - С$.







Ответы

1	1
2	2
3	2
4	3
5	4
6	2
7	3
8	-1
9	2
10	4
11	1
12	4
13	2
14	4
15	2
16	-3
17	0
18	1
19	3
20	1
21	4
22	4
23	-1
24	2
25	1
26	1
27	4
28	2
29	5
30	5