































Вычисление числа степеней свободы механической системы

Определить число степеней свободы системы по формуле $W = 3D - 2Ш - С$.

<p>Вариант 1 Д22.</p> 	<p>Вариант 2 Д22.</p> 
<p>Вариант 3 Д22.</p> 	<p>Вариант 4 Д22.</p> 
<p>Вариант 5 Д22.</p> 	<p>Вариант 6 Д22.</p> 
<p>Вариант 7 Д22.</p> 	<p>Вариант 8 Д22.</p> 
<p>Вариант 9 Д22.</p> 	<p>Вариант 10 Д22.</p> 





Ответы

1	2
2	-2
3	1
4	4
5	3
6	2
7	1
8	4
9	0
10	4
11	3
12	2
13	2
14	3
15	2
16	4
17	1
18	4
19	2
20	2
21	1
22	3
23	3
24	4
25	-3
26	3
27	4
28	2
29	3
30	3