































Вычисление числа степеней свободы механической системы

Определить число степеней свободы системы по формуле $W = 3Д - 2Ш - С$.

<p>Вариант 1 Д22.</p> 	<p>Вариант 2 Д22.</p> 
<p>Вариант 3 Д22.</p> 	<p>Вариант 4 Д22.</p> 
<p>Вариант 5 Д22.</p> 	<p>Вариант 6 Д22.</p> 
<p>Вариант 7 Д22.</p> 	<p>Вариант 8 Д22.</p> 
<p>Вариант 9 Д22.</p> 	<p>Вариант 10 Д22.</p> 





Ответы

1	6
2	1
3	3
4	5
5	1
6	2
7	2
8	0
9	1
10	-1
11	6
12	2
13	2
14	4
15	4
16	0
17	3
18	2
19	1
20	5
21	3
22	3
23	-1
24	3
25	4
26	4
27	2
28	1
29	4
30	5